GE Sensing & Inspection Technologies

Druck UPS-II

Loop Calibrator

User manual - K0434



Find Quality Products Online at: www.GlobalTestSupply.com sales@GlobalTestSupply.com

Approved Service Agents

For the list of service centres visit our web site: www.gesensinginspection.com

Symbols



This equipment meets the requirements of all relevant European safety directives. The equipment carries the CE mark.



Do not dispose of this product as household waste. Use an approved organisation that collects and/or recycles waste electrical and electronic equipment. For more information:

Contact us at www.gesensinginspection.com

Battery Safety

This instrument is fitted with four size AA batteries either rechargeable (nickel cadmium) or non-rechargeable (alkaline).

Before storing this instrument remove the batteries.

When fitting batteries make sure the electrical contacts are clean and observe the correct polarity.

The battery compartment should be inspected for corrosion caused by leaking batteries. Corrosion must be removed using approved methods*.

When storing and transporting batteries make sure that they cannot be short circuited. A short-circuited battery can become very hot and can, in certain circumstances, explode. It is recommended that a suitable container is used for storing and transporting batteries.

Dispose of old batteries using a safe, approved method.*

*Refer to the manufacturer for this information:

© General Electric Company. All rights reserved.

Find Quality Products Online at:

www.GlobalTestSupply.com

Introduction

The Druck UPS-II Loop Calibrator can supply power (source mode) and produce readings (measure mode) to perform field calibrations on 2-wire devices.

Operation For different applications place switches in position as

Milliamp. source	•			•
MODE	OUT	READ	EXT.	INT.
indicated below:	•			

Transmitter sim. Milliamp measure

Transmitter cal.

(transmitters are 4-20mA 2 wire) The UPS-II has special functions for fixed steps and readings

in %. To open menu p	ress * for 2	seconds. Scroll menu	
contents with $\mbox{\mbox{\sc t}}$ key and make your choice. Press * again to confirm your choice.			
MENU CHOICE	SWITCH	DISPLAY READING IN:	
4-20mA lin #	out	0 to 22mA or % span	

LIEINO CHOICE	JVVIICII	DISI LAT ILADINO IIV.
4-20mA lin #	out	0 to 22mA or % span
0-20mA lin	out	0 to 22mA or % span
4-20mA flow	out	0 to 22mA or % span
0-20mA flow	out	0 to 22mA or % span

Press mA/% key to read in mA or %. Press * to select

"continuous" or "fixed steps" in output mode. Fixed Steps To output fixed calibration currents in series as indicated

below: choose range from the menu and select "fixed steps". Press \uparrow or \downarrow to advance one step 4-20mA lin# 4 - 8 - 12 - 16 - 20mA

3,8-4-4,2 - 12 - 19 - 20 - 21mA

K0434 Issue No. 2

To output these currents automatically select "fixed steps" and press $\uparrow \downarrow$ keys simultaneously. Time between steps is 10 seconds. Stepping starts at the low end of span. To return to manual press \uparrow or \downarrow .

Valve mode
In the valve mode, stepping will be 3,8 - 4 - 4,2 or 19 - 20 - 21
mA. Select appropriate current to start auto-stepping.

Ramp mode

To output a continuous up/down ramp cycle press ↑ ↓ keys simultaneously. Ramp travel time between range limits is 60 seconds cycle starts at displayed value. Press ↑ or ↓ first


to select start direction. To return to manual press † or ↓. **Batteries**Use alkaline or rechargeable NiCad batteries only. The display shows **LOBAT** when battery capacity goes low.

CAUTION


DO NOT LEAVE DISCHARGED BATTERIES IN THE INSTRUMENT.

OLD BATTERIES CAN LEAK AND CAUSE CORROSION.


WHEN FITTING THE BATTERIES MAKE SURE THE ELECTRICAL CONTACTS
ARE CLEAN AND OBSERVE THE CORRECT POLARITY




Find Quality Products Online at: www.GlobalTestSupply.com sales@GlobalTestSupply.com







Transmitter Calibration
Switch positions
Function Loop power
Read Int.




K0434 Issue No. 2

Find Quality Products Online at:

www.GlobalTestSupply.com

3



K0434 Issue No. 2

 $\textbf{Find Quality Products Online at:} \qquad \textbf{www.GlobalTestSupply.com} \qquad \textbf{sales@GlobalTestSupply.com} \\$

Calibration Instructions

General

A calibration period of 12 months is recommended. The actual calibration interval depends on instrument usage and the total measurement uncertainty acceptable for the specified application.

The UPS-II is a precise measuring instrument and the test equipment and conditions of test must be suitable for the type of work. The calibration check and calibration adjustment should be carried out in a controlled environment by a calibration technician*.

The manufacturer offers a comprehensive and, if required, UKAS accredited calibration service.

 A calibration technician must have the necessary technical knowledge, documentation, special test equipment and tools to carry out the calibration work on this equipment.
 Calibration Equipment

The following tables give the accuracy requirements for the

calibration equipment and the UPS-II.

Calibration requires a stable temperature of 21° ±1°C (70° ±2°F).

UPS-II measure mode

Table 1

Applied mA	Permitted UPS-II error (mA)	Calibrator error (mA)
0	0.007	0
4	0.007	0.00014
12	0.007	0.00030
20	0.007	0.00046

UPS-II source mode

Table 2

Applied mA	Permitted UPS-II error (mA)	Calibrator error (mA)
0	0.01	0
4	0.01	0.00012
12	0.01	0.00011
20	0.01	0.00015

K0434 Issue No. 2

Calibration Check

 Check the instrument for accuracy in measure and source modes, if there is an error greater than the permitted error, the instrument requires a calibration adjustment.


Calibration Adjustment

Note: For complete accuracy, the measure mode and source mode adjustment must be carried together and in the following order.

Measure mode

- Connect the UPS-II to the electrical calibrator. Switch on the electrical calibrator and allow it to thermally stabilise.
 Switch on the UPS-II and allow the instrument to
- thermally stabilise.

 3. Select EXT on the LOOP PWR slide switch. Use the



Input calibration complete new offset values stored continue with output calibration.

K0434 Issue No. 2


6

sales@GlobalTestSupply.com

Find Quality Products Online at: www.GlobalTestSupply.com

Source mode

- Connect the UPS-II to the electrical calibrator. Switch on the electrical calibrator and allow it to thermally stabilise.
- Switch on the UPS-II and allow the instrument to thermally stabilise.
 Select INT on the LOOP PWR slide switch. Use the 3.



Completion

- Switch off and disconnect the calibration equipment.
- Update the calibration records for the instrument.

K0434 Issue No. 2

Specifications

Range	
External loop power	
Measurement input	
Drive capability	
Operating temperature10°C to 50°C - 14°F to 122°F	
Storage temperature20°C to 60°C4°F to 140°F	
Battery 4 x 1.5V alkaline or rechargeable size AA	
Battery life (alkaline)source 12mA; 18 hours	
measure 900 hours	
Loop mismatch flashes "LOOP"	
Low battery flashes "LOBAT"	
Over-range	
Reversed polarity flashes "POL"	
Adaptor line/6VDC	
230V/50Hz part numbers - UNO-13600-1 (UK)	
- UNO-13600-2 (Europe)	
110V/60Hz part number - UNO-13600-3 (USA)	
Housing high impact ABS	
Size	
Weight 212 grams - 7.5 oz	
(including batteries)	

K0434 Issue No. 2 8